



Issues with the Most Recent Shipment from WSU → Yale
Arrived 3-Jan-2018
5 GEM4


O-ring under GTS cover was not in groove at one end, broken and crushed in two places.
Fortunately contents were still clean.







I-G4-019 – frame not machined properly. The wells for soldering to the bottom HV pads are missing.



I-G4-020 – frame us machined properly.
The wells for soldering to the bottom HV
pads are present.

